

Modificationcard for: Online kit Primesett 74/EG901	Part No. 464001
--	------------------------

Print Date: 07/11/2002

DATE	Lev.	+	Tekst (DK).	Description
15/3-00	1		Første conv. øverste guide over indgang er løs del som clips's på skruehoveder.	1.st. conveyor. Upper guide at entrance is detachable.
23/3-00	2		Nyt conveyor print 464609 + div. nye cableset i conveyor	New Conveyor PCB 464609+ new cablesets inside conveyor
18/4-00	3		Conveyor motor kable skærmet og i separat stik.	Conveyor motor cable shielded and in separate plug
25/5-00	4	+	Conveyor cableset 464423 m. parsnoet kabel + skærmet motorkabel til conveyor print	Conveyor cableset 464423 with twisted pair cable + screened cable for conv. motor
25/5-00	5	+ (fra 14/8)	Nyt interface PCB i controlbox 305410 samt nyt conveyor kable 464424 for speedway kommunikation CPU print skal være 305110 for at passe til kabel	New interface PCB in controlbox 305410 New conveyor cableset 464424 for speedway communication CPU board must be 305110 to fit new conveyor cable
19/4-00	6		Conveyor forberedt for hæve/sænke valser	Conveyor prepared for open/close rollers
12/7-00	7	+	Fladkabel 464422 med kortslutning fra pin 12 til pin 10 som forsyning til MIDO print	Flatcable 464422 with a shot circuit pin 12 to pin 10 for supply of MIDO board
13/9-00	8		Ny low inletguide 464085 rev. G.	New low inletguide 464085 rev. G.
21/9-00	9		464609 conv. Print 15 pol sub-D stik lige model.	464609 conv. Circuit board 15 pol sub-D connector straight model.
27/2-01	10	+	Forstærkningsbjælke 464040 monteres under conveyor låg ca 220mm fra forkant	464040 Support f. lid Primeset. 102 under conveyor lid apprx. 220mm from front edge
27/2-01	11	+	Skrå læbe i bund hvor film kommer ind fra Primesetter afkortet fra 35mm til 15mm	Inclined lip in conveyorbottom where film comes in from Primesetter shorter from 35mm to 15mm
27/2-01	12	+	Top inlet guide 464084 med 2 fixerings huller. Guide afkortet når ikke længere conv. bund	Top inlet guide 464084 with 2 fixerings holes. Guide does not rech conv. bottom.
30/5-01	13	+ for EGP	Ny 464088 OutletGuide MK2 primesett. 74 erstatter 464081. Knæk flyttet længere ind i conveyor for at justere diverterguide combi lettere	New 464088 OutletGuide MK2 primesett. 74 replaces 464081. Ben is further inside conveyor to ease adjustment of diverterguide in combi.
30/4-02			Outlet guide tilbage undtagen GL combi	

